



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3126-5

Job Sheet 200476



DAS
21
9-30

Part No: D3126-5

Job Qty: 6 pcs

Part Name: Bracket



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/11/19

Job Tracking No:

Due Date: 10/10/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV A1 IPP: A 03.01.15 New issue KJ/RF IPP Rev:B 08-01-15 now on water jet DD

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Waterjet - Flow - 1	6 pcs		10/10/19	0.17	0.28	Waterjet - Flow		DL19/10/21
110	QC 2	6 pcs		10/10/19	0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		DL19/10/21
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		
							QC 2 - 64		

Plex 9/11/19 2:57 PM Dart.lajeunesse.marie

120	QC 8	6 pcs	10/10/19	0.00 0.00	QC 2 - 65	
					QC 2 - 5	
					QC 2 - 71	
					QC 2 - 73	
					QC 2 - 69	
					QC 8 - 12	
					QC 8 - 14	
					QC 8 - 17	
					QC 8 - 20	
					QC 8 - 25	
					QC 8 - 3	
					QC 8 - 32	
					QC 8 - 33	
					QC 8 - 35	
					QC 8 - 39	
					QC 8 - 4	
					QC 8 - 44	
					QC 8 - 45	
					QC 8 - 49	
					QC 8 - 58	
					QC 8 - 8	
					QC 8 - 9	
					QC 8 - 68	
					QC 8 - 67	
					QC 8 - 1 (A)	
					QC 8 - 47	
					QC 8 - 40	
					QC 8 - 52	
					QC 8 - 23	
					QC 8 - 57	
					QC 8 - 76	
130	Small Fab - Brake NC - B4B	6 pcs	10/10/19	0.25 0.30	Small Fab - Brake - 1 - B4B	DAS 30 9-89 OCT 2 4 2019
					Small Fab - Brake - 2 - B4B	
					Small Fab - Brake - 3 - B4B	
140	QC 5	6 pcs	10/10/19	0.00 0.00	QC 5 - 10	
					QC 5 - 12	
					QC 5 - 17	
					QC 5 - 18	
					QC 5 - 19	
					QC 5 - 22	
					QC 5 - 24	
					QC 5 - 3	
					QC 5 - 43	
					QC 5 - 49	
					QC 5 - 51	
					QC 5 - 58	
					QC 5 - 68	
					QC 5 - 9	
					QC 5 - 50	
					QC 5 - 30	
					QC 5 - 40	
					QC 5 - 61	
					QC 5 - 81	
150	Packaging 3-1 - Stock - B4B	6 pcs	10/10/19	0.00 0.00	Packaging 3 - 1 - B4B	
					Packaging 3 - 2 - B4B	
					Packaging 3 - 3 - B4B	
					Packaging 3 - 4 - B4B	

				Packaging 3 - 5 - B4B	
				Packaging 3 - 6 - B4B	
				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	PC CA002
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	DAS
160 QC 21 - SA	6 pcs	10/10/19	0.00 0.00	QC 21 - SA - 21	21
				QC 21 - SA - 70	70
				QC 21 - SA - 53	OCT 25 2019

Part Op **100** - 1-Cut as per Dwg D3126 Dwg Rev: AI Prog Rev: AI 2-Deburr if necessary
 Descriptions: **110** - QC2- Inspect parts off machine FAI/FAIB
120 - QC8- Inspect parts - second check
130 - (Bend/Assemble as per dwg), 1-Form on CNC brake as per D3126 using Jig D3126T1 Identify as D3126-5 2-Scribe Dart P/N as shown on Dwg D3126
140 - QC5- Inspect part completeness to step on W/O
150 - Identify as per dwg & Stock Location: _____
160 - QC21- Final Inspection - Work Order Release

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
M304S22GA	304/316 .032 Sheet	.7200 sf (.12 ea)	100-Waterjet - Flow - 1	5021857

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Waterjet - Flow - 1	M304S22GA	1	98	0

Part Specifications					
Spec No	Description	Target/Tolerance	Limits	Type	Special Comments
1	Bracket	0.200Inches $\pm$ 0.010	0.210 0.190		
2	Bracket	0.260Inches $\pm$ 0.010	0.270 0.250		
3	Bracket	0.800Inches $\pm$ 0.010	0.810 0.790		
4	Bracket	1.830Inches $\pm$ 0.010	1.840 1.820		
5	Bracket	1.910Inches $\pm$ 0.010	1.920 1.900		
6	Bracket	2.300Inches $\pm$ 0.010	2.310 2.290		
7	Bracket	2.832Inches $\pm$ 0.010	2.842 2.822		
8	Bracket	2.825Inches $\pm$ 0.010	2.835 2.815		
9	Bracket	4.600Inches $\pm$ 0.010	4.610 4.590		
10	Bracket	5.650Inches $\pm$ 0.010	5.660 5.640		
11	Bracket	0.032Inches $\pm$ 0.010	0.042 0.022		

Plex 9/11/19 2:57 PM Dart.lajeunesse.marie

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐



Job: _____ Part No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐		DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐		Cross tube ☐ Small Fab ☐ Finishing ☐		Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐		Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐																													
Date :		Sequence #:		QTY Affected :		MRB (QS1042)																																	
Description Work Order Deviation				Disposition																																			
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐				FAULT CATEGORY <table border="1"> <tr> <td>Pressure/Forced</td> <td>Contamination</td> <td>Power Loss/Surge</td> <td>Positioned Wrong</td> </tr> <tr> <td>Bending</td> <td>Misaligned/off center</td> <td>Folio/Program</td> <td>Outside Tolerance</td> </tr> <tr> <td>Crushing</td> <td>BOM/Route</td> <td>Grain Direction</td> <td>Drawing</td> </tr> <tr> <td>Cracks</td> <td>Broken/Damage/Defect</td> <td>Weld</td> <td>Finish</td> </tr> <tr> <td>Crimp/Kink/Ripple/Wave/Twist</td> <td>Incomplete/Unclear Instructions</td> <td>Wrong Stock Pulled</td> <td>Part Lost/Missing</td> </tr> <tr> <td>Marks/Chatter</td> <td>Drill Holes</td> <td>Out of Sequence</td> <td>Misread</td> </tr> <tr> <td>Mislabeled</td> <td>Fit/Function</td> <td>Off-set/Set-up</td> <td></td> </tr> </table>								Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong	Bending	Misaligned/off center	Folio/Program	Outside Tolerance	Crushing	BOM/Route	Grain Direction	Drawing	Cracks	Broken/Damage/Defect	Weld	Finish	Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing	Marks/Chatter	Drill Holes	Out of Sequence	Misread	Mislabeled	Fit/Function	Off-set/Set-up	
Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong																																				
Bending	Misaligned/off center	Folio/Program	Outside Tolerance																																				
Crushing	BOM/Route	Grain Direction	Drawing																																				
Cracks	Broken/Damage/Defect	Weld	Finish																																				
Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing																																				
Marks/Chatter	Drill Holes	Out of Sequence	Misread																																				
Mislabeled	Fit/Function	Off-set/Set-up																																					
Other/Details:																																							
				Completed By Lead hand / Supervisor QC / QA Coordinator																																			